

25X1A

ORIG :   
 UNIT : DPD/DB   
 EXT : 8813   
 DATE : 30 NOVEMBER 1960

CLASSIFIED MESSAGE

CH/OPS BR   
 SECRET

ROUTING

1	DPD/DB	5	DPD/OPS
2	G/DPD/DB	6	ACH/DPD
3	C/DPD/DB	6	DPD/RT

TO : 25X1A

FROM : DIRECTOR

CONF: DPD (1,2,3,4,5,6,7,8,9,10)

INFO : S/C (11)

DND

TOR: 2246Z 30 NOV 60

PR.

PR.

AIR

INTEL

CONTROL

WX

INITIAL WHEN READ

DEFERRED

PRIORITY

INITIALS

ROUTINE

OPERATIONAL  
IMMEDIATE

INITIALS

OUT 76533

25X1A

TO (PRITY) 25X1A INFO

SITE

5350

25X1A

FORWARDED FOLLOWING INFORMATION ON MISSION G3003 OF CONCERN TO YOU:

9R SIDE SHOWS A DE-SENSITIZED SPOT 2 AND 5/16 INCHES IN FROM DATA CHAMBER EDGE 25X1A  
 AND APPEARS AT SAME FREQUENCY LONGITUDINALLY. BELIEVES THIS IS CAUSED BY  
 APPROXIMATELY .74  
 A CAMERA ROLLER WITH A DIAMETER OF APPROXIMATELY .74 INCHES. NINE INSTANCES OF  
 SHUTTER MALFUNCTION IN FIRST 75 FRAMES AND ANOTHER INSTANCE AT ABOUT FRAME 150.  
 VACUUM TROUBLE WAS NOTICEABLE BUT NOT TOO SERIOUS, RESOLUTION FAIR. DATA CHAMBER  
 NOT AS LEGIBLE AS USUAL. EXPOSURE ADEQUATE, NO CHANGE ADVOCATED.

END OF MESSAGE

DPD/OPS

This document contains information  
 referring to Project CORONA

25X1A

COORDINATING OFFICERS

SECRET

C/DB/DPD

RELEASING OFFICER

MAJOR

USAF

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED

Copy No.